

FIG. 4

FIG. 5

A hand-drawn cross-sectional diagram of a mechanical assembly. The diagram shows a central vertical component with a series of notches or teeth along its left edge. To the right of this component is a vertical plate or wall. Dimensions are indicated by arrows and text:

- 5"**: Dimension at the top right, pointing to a horizontal section.
- 10"**: Dimension on the left, pointing to a horizontal section.
- 20"**: Dimension on the right, pointing to a horizontal section.
- 4"**: Dimension on the right, pointing to a horizontal section.
- 14"**: Dimension on the left, pointing to the height of the notched section.
- 12"**: Dimension on the right, pointing to the height of the central component.
- 26**: Label pointing to one of the notches on the left.
- 42**: Label pointing to the central component.
- 45**: Label pointing to one of the notches on the left.
- 44**: Label pointing to the central component.
- 24**: Label pointing to one of the notches on the left.
- 47**: Label pointing to the central component.
- 50**: Label pointing to one of the notches on the left.
- 6"**: Dimension on the right, pointing to a horizontal section.
- 16"**: Dimension on the right, pointing to a horizontal section.
- 30**: Label pointing to a vertical dashed line on the right.
- 28**: Label at the bottom right, pointing to a horizontal dashed line.

© 2000 Blackwell Science Ltd



[illegible]

FIG. 8

007580 0052550




FIG. 9




FIG. 10